

CTCV - Medição e Ensaio
Laboratório de Ensaio de Produtos

TEST REPORT Nº 15.1001/2024
Sample ref. 2024.2.438.LAC


Client	Cerâmica de Boialvo, Lda.	Process nº	21.49937
Address	3780-401 Avelãs de Cima		
Material	Ceramic vessels	Test date	02/02/2024
Client ref. (*)	Colour Antique Water-repellent	Entrance date	03/01/2024

DETERMINATION OF FROST RESISTANCE

(according UNI 8635-11:1984)

Visual inspection after 25 cycles of freeze-thaw

Small cracks located close to the water drainage hole



CONCLUSION

The vessel maintains its functionality after exposure to 25 freeze/thaw cycles (-15°C /+15°C)

Note: Sampling under client responsibility.

(*) Information given by client.

COIMBRA, 09 February 2024

Laboratory Technician

Marco Oliveira

Head of Laboratory

Joaquim Valente de Almeida